




## Brazing in five *easy* steps...




**1** Clean the rail to a bright finish




**2** Load the gun with a pin and ferrule



**3** Adjust as necessary



**4** Braze



**5** Test the connection